




Typical Temperature Range of Insulation and Jacket Materials

Temperatures may vary depending on formulation of compound.
All Temperature Degree Centigrade



TEMPERATURE CONVERSION FORMULA

$C = \frac{5}{9} (F - 32)$

$F = \frac{9}{5} (C + 32)$